


Index No. J1

CASS COUNTY LAND CORNER RECORD

T. 136 R. 32 M. 5TH Coordinates: X _____ Y _____
NW 18 Corner common to sections 7, 18 AND 12, 13 - 136-33



EXISTING SURVEYS

Original Government Survey
Year surveyed 1858
Original monument POST

Original Evidence Found
Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	ASPEN	ASPEN	ASPEN	ASPEN
Diameter	<u>6"</u>	<u>6"</u>	<u>7"</u>	<u>5"</u>
Bearing	<u>S14E</u>	<u>N72E</u>	<u>N72W</u>	<u>S53W</u>
Distance	<u>23 LKS</u>	<u>27 LKS</u>	<u>32 LKS</u>	<u>25 LKS</u>

Original Bearing Trees Found				
Species				
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration
Year surveyed 1916 By E. B. HORST
Location filed COUNTY BOOK "B" P. 542-544
Monument FIND 2 STUMPS THAT CHECK WITH OLD CORNER NOTES SET F.M.
also on microfilm - roll 105 BK 65 P. 24, 62

Evidence of Subsequent Corner Restoration
Year of search _____ By _____

Bearing Trees, Reference Objects			
Species	<u>F.P.</u>	<u>W. PINE</u>	<u>W. PINE</u>
Diameter	<u>14"</u>	<u>14"</u>	<u>12"</u>
Bearing	<u>EAST</u>	<u>N81-30W</u>	<u>S61-30W</u>
Distance	<u>32.4'</u>	<u>304.0'</u>	<u>170.6'</u>

Bearing Trees, Reference Objects				
Species				
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____