

Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration


Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Index No. N1

CASS COUNTY LAND CORNER RECORD



T. 136 R. 32 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NW 19 Corner common to sections 18, 19 AND 13, 24-136-33

EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1858  
 Original monument Post

| Species        | Bearing       | Trees         |
|----------------|---------------|---------------|
| <u>W. Pine</u> | <u>OAK</u>    | <u>ASPEN</u>  |
| <u>7"</u>      | <u>10"</u>    | <u>14"</u>    |
| <u>557E</u>    | <u>535W</u>   | <u>N58W</u>   |
| <u>75 LKS</u>  | <u>65 LKS</u> | <u>87 LKS</u> |

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
| _____   | _____    | _____   | _____    |
| _____   | _____    | _____   | _____    |
| _____   | _____    | _____   | _____    |
| _____   | _____    | _____   | _____    |

**Subsequent Corner Restoration**  
 Year surveyed 1918 By E. B. Horst  
 Location filed COUNTY BOOK "C" P. 107  
 Monument FIND WOOD POST FOR CORNER SET OAK WITNESS  
POSTS N45E, S45E 46.7'  
also on microfilm - roll 105BK 65 P. 66-67

**Evidence of Subsequent Corner Restoration**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

**Bearing Trees, Reference Objects**

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
| _____   | _____    | _____   | _____    |
| _____   | _____    | _____   | _____    |
| _____   | _____    | _____   | _____    |
| _____   | _____    | _____   | _____    |

**Bearing Trees, Reference Objects**

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
| _____   | _____    | _____   | _____    |
| _____   | _____    | _____   | _____    |
| _____   | _____    | _____   | _____    |
| _____   | _____    | _____   | _____    |

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_