


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration


Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. R1

CASS COUNTY LAND CORNER RECORD



T. 136 R. 32 M. 5TH Coordinates: X 19,30 AND Y 24,25-136-33
NW. 30 Corner common to sections

EXISTING SURVEYS

Original Government Survey

Year surveyed 1856
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing	Trees	
Species	<u>SP. PINE</u>	<u>Y. PINE</u>	<u>TAM</u>
Diameter	<u>12"</u>	<u>14"</u>	<u>5"</u>
Bearing	<u>S10E</u>	<u>S23W</u>	<u>N9E</u>
Distance	<u>30 LKS</u>	<u>51 LKS</u>	<u>52 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1926 By GREENE
Location filed COUNTY BOOK "D" P. 171
Monument FWO CORNER

Evidence of Subsequent Corner Restoration

Year of search 10/1904 By W. Hallett
Surveyor's Report, Top. Road Order
Shows Road on North line Sec.
30.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remuneration certificate prepared _____ By _____
Filed at _____ Date _____