Index No. V 13

CASS COUNTY LAND CORNER RECORD

T. 136 R. 32 M. 5TH Coordinates: X _____ Y _____

NE 33 Corner common to sections 27, 28, 33, 34



EXISTING SURVEYS

Original Government Survey

Year surveyed 1866

Original monument Post

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species	BL. PINE	BL. PINE	BL. PINE	BL. PINE
Diameter	6"	8"	8"	6"
Bearing	S 50½ W	N 53 W	N 73½ E	S 63 E
Distance	12 LKS.	8 LKS	33 LKS	37 LKS

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration

Year of search 2000 By CCSO

Fnd. inplace 1¼" sq. pipe. Located 26' ± N of fence running E/W, and 1' E of fence So. Is 6' S of ℄ trail and 36' ± to ℄ mid pt. of Curve.

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

R. Pine	R. Pine	J. Pine	P. Pole
7"	10"	10"	
N 38° E	S 6° E	S 54° W	N 46° W
70.20'	41.80'	20.65'	51.36'

* dist. to dbl. hd. nail

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____