

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 136 R. 32 M. 5TH Coordinates: X _____ Y _____
NE 36 Corner common to sections 25, 36 and 30, 31-136-31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1858
 Original monument Post

Original Evidence Found

Year of search _____ By _____
 Monument found _____

	Bearing Trees			
Species	<u>Aspen</u>	<u>Aspen</u>	<u>Ironwood</u>	<u>OAK</u>
Diameter	<u>7"</u>	<u>7"</u>	<u>6"</u>	<u>17"</u>
Bearing	<u>N56E</u>	<u>N81 1/4 W</u>	<u>S 71 1/2 E</u>	<u>S 36 1/2 W</u>
Distance	<u>27 LKS</u>	<u>25 LKS</u>	<u>16 LKS.</u>	<u>21 LKS.</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1916 By JOHN CRO (Baldwin)
 Location filed COUNTY SURVEY RECORD BOOK "B" P. 47-257
 Monument SET PROPORTIONALLY
1923 - JOHN GREENE - COUNTY RESURVEY "E-45" I.M.
1928 - JOHN GREENE - COUNTY RESURVEY PLATE "E-68" I.M.

Evidence of Subsequent Corner Restoration

Year of search 1922 By E. B. Horst
COUNTY BOOK "D" P. 79 - FIND CORNER AND BALDWIN'S B.T.S
1922, Horst, Book "D" P. 163 - FIND CORNER & BALDWIN'S B.T.S
IN 1925 - P. 180 - BOOK D - GREENE SET 120 N

1916 - also on microf. film - roll 105 BK 67 P. 37

Bearing Trees, Reference Objects

Species	<u>ELM</u>	<u>ELM</u>	_____	_____
Diameter	<u>8"</u>	<u>3"</u>	_____	_____
Bearing	<u>N 28 W</u>	<u>N 71 - 30 E</u>	_____	_____
Distance	<u>54.70'</u>	<u>44.40'</u>	_____	_____

1916 TIES

Bearing Trees, Reference Objects

Species	<u>ELM</u>	<u>ELM</u>	_____	_____
Diameter	<u>6"</u>	<u>7"</u>	_____	_____
Bearing	<u>N 60 E</u>	<u>N 37 W</u>	_____	_____
Distance	<u>44'</u>	<u>54.8'</u>	_____	_____

1925 TIES

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search 1999 By CCSO
Find. incl. Alum. cap. mon. down 0.3'
Located @ CR 109 @ 27' N of driveway to
the east. found (4) B.T. tags w/ descriptions

REF. TIES:

<u>9" Basswood clump</u>	<u>N 59° W</u>	<u>64.55'</u>
<u>fence post</u>	<u>N 59° E</u>	<u>60.66'</u>
<u>P. Pole</u>	<u>S 12° E</u>	<u>122.72'</u>
<u>11" Aspen</u>	<u>S 21° W</u>	<u>221.55'</u>

*distances to find. 60d spk.