


Index No. X 13

CASS COUNTY LAND CORNER RECORD

T. 136 R. 32 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 33 Corner common to sections 33, 34



EXISTING SURVEYS

Original Government Survey

Year surveyed 1866  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>BL PINE</u>	<u>BL PINE</u>		
Diameter	<u>10"</u>	<u>6"</u>		
Bearing	<u>N88W</u>	<u>S34 1/2 E</u>		
Distance	<u>37 LKS</u>	<u>37 LKS</u>		

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 2000 By CCSO  
Location filed Cass Co.  
Monument Set 2" x 18" te/spar pipe w/ cap  
stamped 1/4 S. 33 RLS 16459, up 0.2.  
Located 20' ± W of N/S Fence and 36' ± S  
of E/W Fence

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>R. Oak</u>	<u>R. Oak</u>	<u>R. Oak</u>
Diameter	<u>15"</u>	<u>4"</u>	<u>8"</u>
Bearing	<u>N 5° W</u>	<u>S 82° E</u>	<u>S 12° W</u>
Distance	<u>13.34'</u>	<u>18.19'</u>	<u>11.48'</u>

(TAG)

Bearing Trees, Reference Objects


Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Re-monumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_