Index No. A 13

CASS COUNTY LAND CORNER RECORD

T. 137 R. 29 M. 5TH Coordinates: X _____ Y _____

NE 4 Corner common to sections 3, 4 AND 33, 34 - 138-29



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865

Original monument POST

Bearing Trees

Species	BL. PINE	BL. PINE	BL. PINE	BL. PINE
Diameter	10"	9"	8"	7"
Bearing	N14E	N30W	S10W	S14E
Distance	17 LKS.	103 LKS.	22 LKS.	30 LKS.

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species				
Diameter				
Bearing				
Distance				

Subsequent Corner Restoration

Year surveyed 1908, 1912 By JOHN CURD, HARRY TODD, Surveyor

Location filed COUNTY SURVEY RECORD BOOK "A" P318-328

Monument SET CORNER FROM OLD 60 in B.TS IN 1912 FND STUMP OF OLD 60in BTS: 10"B. PINE N14E 17LKS, 8"B. PINE S10W 22LKS, 9"BL. PINE N30W 103LKS, 7" BL PINE S14E 30LKS SET 2 1/2 x48" CAPPED 64LU. 1 PIN CONCRETE

Bearing Trees, Reference Objects

Species	J. PINE STUMP	J. PINE		
Diameter	10"	6"		
Bearing	N39-16E	N71-30W		
Distance	16.70'	52.50'		

Evidence of Subsequent Corner Restoration

Year of search AUG. 2000 By CCSO

Fnd. inplace; CIM 4". 4' steel post on East side mon. Located 120'± S of ℄ CSAH 2 and 31' N of CFP

Bearing Trees, Reference Objects

W. Oak	J. Pine	J. Pine	J. Pine
6"	6"	11"	8"
N 62°W	N 54°E	S 68°E	S 15°W
75.21'	12.96'	45.48'	63.02'

* distance to dbl. hd. nail

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument - Corner GPS 9/18/02 CCSO

CIM, flush, on fence line

Jan. 1992 D. Landecker #17008

Cert. of survey shows monument found

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____