

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____


Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

T. 137 R. 29 M. 5th Coordinates: X _____ Y _____
NE 8 Corner common to sections 4, 5, 8, 9



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
 Original monument lost

Original Evidence Found

Year of search _____ By _____
 Monument found _____

Bearing Trees

Species	<u>N. Pine</u>	<u>Bl. Pine</u>	<u>Bl. Pine</u>	<u>Bl. Pine</u>
Diameter	<u>24"</u>	<u>6"</u>	<u>8"</u>	<u>6"</u>
Bearing	<u>N 73 E</u>	<u>N 17 W</u>	<u>S 45 W</u>	<u>S 19 E</u>
Distance	<u>—</u>	<u>21 LKS</u>	<u>15 LKS</u>	<u>29 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1906 By JOHN CUREO
 Location filed COUNTY SURVEY RECORD BOOK 'A' P 318-328
 Monument SET CORNER
IN 1909 FIND CORNER
BOOK 'C' P 474, ROAD SURVEY, IRON MONUMENT

Evidence of Subsequent Corner Restoration

Year of search 1942 By JOHN CUREO
COUNTY BOOK 'D' P 306 R.R. SPIKE FOR CORNER

Bearing Trees, Reference Objects

Species	<u>J. Pine</u>	<u>J. Pine</u>	<u>J. Pine</u>	<u>J. Pine</u>	<u>DEAD J. Pine</u>
Diameter	<u>12"</u>	<u>12"</u>	<u>12"</u>	<u>11"</u>	<u>10"</u>
Bearing	<u>N 64-31 W</u>	<u>N 41-30 W</u>	<u>N 56-58 W</u>	<u>N 32-13 W</u>	<u>S 71-9 E</u>
Distance	<u>34.3'</u>	<u>48.2'</u>	<u>34'</u>	<u>47.33'</u>	<u>8.95'</u>
	<u>^ 1906 B.T.S A</u>		<u>^ 1909 B.T.S J</u>		

Bearing Trees, Reference Objects

Species	<u>J. Pine</u>	<u>J. Pine</u>	<u>W. Pine</u>	<u>PIPE</u>
Diameter	<u>4"</u>	<u>11"</u>	<u>36"</u>	<u>2x48"</u>
Bearing	<u>N 39 E</u>	<u>S 65 E</u>	<u>S 35 W</u>	<u>N 48-30 W</u>
Distance	<u>41.25'</u>	<u>81.80'</u>	<u>252.70'</u>	<u>47.40'</u>

E-9

Subsequent Corner Restoration

Year surveyed 1983 By Freeman i Stevenson
 Location filed Found 2" I.P. for corner.
 Monument Found Stump of 1942 B.T - 11" J. Pine
S 65 E 82.4' and 2" I.P. N 48 W 46.95'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - C.J. BARK - BEST LAND ENGINEER - 1982
Set 2" hollow iron pipe 3'6" long. TIES:
2" hollow iron pipe NE 46.7'; 2" hollow iron
pipe SE 46.7'; 2" hollow iron pipe SW 46.7';
2" hollow iron pipe NW 46.7'.

1904 - J.H. Hallett - Twp. Rd. Order
indicates corner and witnesses!
12" J. Pine N 64° 30' W, 52 lks (34.3')
12" J. Pine N 41° 30' W, 73 lks (48.2')