


T. 137 R. 30 M. 5TH Coordinates: X _____ Y _____
N 114 3 Corner common to sections 3 AND 34-138-30



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1865
 Original monument Post

Species	Bearing	Trees
<u>Bl. Pine</u>	<u>Bl. Pine</u>	
Diameter <u>10"</u>	<u>8"</u>	
Bearing <u>S 19 1/2 E</u>	<u>N 19 1/2 E</u>	
Distance <u>13 LKS.</u>	<u>33 LKS.</u>	

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration
 Year surveyed 1911 By A. W. MOULSTER
 Location filed COUNTY SURVEY RECORD BOOK "A" P 536
 Monument END STAKES OF OLD GOVT B.T.S: 10" BL. PINE
S 19-30 E 13 LKS, 8" BL. PINE N 17-30 E 33 LKS.
SET 2x48" GALV. I.P. IN CONCRETE B.T.S. ACTUAL
STAND 524-526 AND N 27-04 E
 also on micro film - roll 105 BK 50 P. 51
 Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>1915-John W. CURR Book B P 108-114 END IRON</u>			

Evidence of Subsequent Corner Restoration
 Year of search 1999 By CCSO
Set PK from Landecker Survey info.
2.2' N. of # 2

Bearing Trees, Reference Objects

Tele. Ped Post	P. Pole	J. Pine	W. Pine
		<u>8"</u>	<u>6"</u>
<u>N 46° E</u>	<u>South</u>	<u>S 60° W</u>	<u>N 40° W</u>
<u>121.90'</u> *	<u>45.23'</u> *	<u>81.85'</u> *	<u>116.30'</u> *

*distance to double head nail

A-15
 Subsequent Corner Restoration
 Year surveyed 1904 By W. H. Hallett
 Location filed Trap Rd orders & Trap file
 Monument Surveyors Report indicates
1/4 stake.

June 2004 B. Grimes # 17253
Cert. of Sur. Shows mon. found

Aug. 1904 W. H. Hallett
Trap Rd order shows survey

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____