


Index No. E13

CASS COUNTY LAND CORNER RECORD

T. 137 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 9 Corner common to sections 3, 4, 19, 10



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1870  
 Original monument POST

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

	Bearing	Trees		
Species	<u>J. PINE</u>	<u>TAM</u>	<u>W. PINE</u>	<u>W. PINE</u>
Diameter	<u>8"</u>	<u>10"</u>	<u>8"</u>	<u>5"</u>
Bearing	<u>N 80 E</u>	<u>S 73 E</u>	<u>S 9 W</u>	<u>N 54 W</u>
Distance	<u>140 LKS.</u>	<u>95 LKS.</u>	<u>105 LKS.</u>	<u>27 LKS.</u>

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed March 2004 By B. Grivna #17253  
 Location filed CSG  
 Monument cert of sur. shows mon. found

Evidence of Subsequent Corner Restoration  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Bearing Trees, Reference Objects  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Remuneration certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_