


Index No. J 13

CASS COUNTY LAND CORNER RECORD

T. 137 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 16 Corner common to sections 9, 10, 15, 16



EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1870  
 Original monument POST

Species	Bearing	Trass	
<u>W. PINE</u>	<u>W. PINE</u>	<u>W. PINE</u>	<u>W. PINE</u>
Diameter <u>17"</u>	<u>9"</u>	<u>12"</u>	<u>18"</u>
Bearing <u>N 87W</u>	<u>S 68W</u>	<u>S 76E</u>	<u>N 44E</u>
Distance <u>7 LKS</u>	<u>24 LKS.</u>	<u>47 LKS.</u>	<u>63 LKS</u>

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration**  
 Year of search DEC. 1919 By \_\_\_\_\_  
Trap rd order shows no survey

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_