


Index No. Z 12

CASS COUNTY LAND CORNER RECORD

T. 137 R. 30 M. 5<sup>th</sup> Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
Corner common to sections 33|137|30 & 4|136|30



EXISTING SURVEYS

**Original Government Survey**

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

**Bearing Trees**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Original Evidence Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration**

Year of search 2000 MAR. By CCSO  
Fnd. in place; 3"x3" sq. felspar cap. flush w/  
bit. located E Co. Rd. 28

**Bearing Trees, Reference Objects**

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

**Bearing Trees, Reference Objects**

<u>R. Oak</u>	<u>R. Oak</u>	<u>Elm</u>	<u>W. Oak</u>
<u>14"</u>	<u>7"</u>	<u>10"</u>	<u>6"</u>
<u>N 41° W</u>	<u>N 45° E</u>	<u>S 20° E</u>	<u>S 24° W</u>
<u>97.70'</u>	<u>96.32'</u>	<u>70.45'</u>	<u>58.55'</u>

\* distance to dbl. hd. nail

**Subsequent Corner Restoration**

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

**Evidence of Subsequent Corner Restoration Found**

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_