


Index No. A 9

CASS COUNTY LAND CORNER RECORD

T. 137 R. 31 M. 5TH Coordinates: X NE 5 Y 4, 5 And 32, 33-137-31
Corner common to sections



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865

Original monument POST

Bearing Trees				
Species	<u>W. BIRCH</u>	<u>N. PINE</u>	<u>N. PINE</u>	<u>W. PINE</u>
Diameter	<u>6"</u>	<u>26"</u>	<u>24"</u>	<u>36"</u>
Bearing	<u>N 21 E</u>	<u>N 62 W</u>	<u>S 80 W</u>	<u>S 30 E</u>
Distance	<u>39 LKS.</u>	<u>24 LKS.</u>	<u>27 LKS.</u>	<u>64 LKS.</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1908 By JOHN CURD

Location filed COUNTY SURVEY RECORD BOOK "A" P 330-340

Monument FIND STUD OF ORIG B.T. 26" N. PINE N 62 W 15.8' ALSO POST OF S.W. B.T. SET 4x4x48" POST

also on microfilm - roll 115PK 95 P. 190-191

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Evidence of Subsequent Corner Restoration

Year of search 9/2002 By CCSO

Dug 6' x 8' x 3', no evidence of corner.

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

A-9

Subsequent Corner Restoration

Year surveyed 8/2005 By CCSO

Location filed #2002.011

Monument Set PK nail, 0.5' North of E. Co. Rd #2, at 1908 prorata distance and 1957 E projection from the East.

15" N. Pine	N 37° W	127.20'	*
10" Maple	N 41° E	106.31'	*
11" Balsam	S 57° E	118.38'	*
13" R. Oak	S 40° W	73.48'	*

*distance to double head nail

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____