

Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Page \_\_\_\_\_ of \_\_\_\_\_

Corner common to sections \_\_\_\_\_


Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

T. 137 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 14 Corner common to sections 11, 12, 13, 14



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument Post

Species	Bearing	Trees
<u>DEAD N. PINE</u>	<u>581E</u>	<u>29 LKS</u>
<u>DEAD N. PINE</u>	<u>N41E</u>	<u>42 LKS</u>
<u>DEAD N. PINE</u>	<u>576W</u>	<u>30 LKS</u>
<u>DEAD <del>PINE</del></u>	<u>N56W</u>	<u>30 LKS</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1915 By J. A. JOHNSTON

Location filed COUNTY BOOK "C" P. 284

Monument SET STAKE FROM NEW BITS! PINE STUMP 8" N11-30E  
52.70', 12" PINE STUMP S58-47E 47.20', 10" N. PINE  
562-45 W 52.30', 8" N. PINE N16-14W 71.70' SET  
2" X 48" T.M.

also on microfilm - roll 115 BK 80 P. 10, 30

Species	Bearing	Trees, Reference Objects
<u>PINE STUMP</u>	<u>N11-30E</u>	<u>8"</u>
<u>PINE STUMP</u>	<u>S58-47E</u>	<u>12"</u>
<u>N. PINE</u>	<u>562-45 W</u>	<u>10"</u>
<u>N. PINE</u>	<u>N16-14W</u>	<u>8"</u>

Evidence of Subsequent Corner Restoration

Year of search 1920 By MORRIS

COUNTY BOOK "C" P. 567 FND I.M.  
1941, JOHN CURR, BOOK "D" P. 258-259 FND 2 X 48" T.M.

Species	Bearing	Trees, Reference Objects
<u>J. PINE</u>	<u>N46-55E</u>	<u>11"</u>
<u>PIPE (WITNESS)</u>	<u>545E</u>	<u>2 X 36"</u>
<u>N. PINE</u>	<u>556-04W</u>	<u>16"</u>
<u>W. PINE</u>	<u>N42-54W</u>	<u>10"</u>

50.95'      46.67'      59.35'      53.43'

1941 TIES

J-21 T.137 R. 31

Subsequent Corner Restoration

Year surveyed 1979 By HWT DEPT.

Location filed \_\_\_\_\_

Monument LOWERED 3" CAPPED IRON PIPE

Evidence of Subsequent Corner Restoration Found

Year of search 9/9/87 By FREEMAN

FOUND 2 1/2" IRON PIPE DOWN 6"

<u>J. PINE</u>	<u>N 47° E</u>	<u>51</u>	<u>STUMP</u>
<u>W. PINE</u>	<u>NW</u>	<u>53</u>	

7/02 CCSSO  
Found 2" ODIP, down 0.2', 2' ± S. of E  
Cord. #25 and 2' ± E of E 52nd Ave.

18" N. Pine N18° E 98.65' to dbl hd nail  
12" N. Pine S28° E 70.86' to dbl hd nail  
16" N. Pine S29° W 90.76' to dbl hd nail  
18" W. Pine N38° W 54.00' to dbl hd nail

Jan 2004 CCSSO J Leas #42619  
Certificate shows monument found  
Sept. 1919; Twp rd order shows no survey