


Index No. P 13

CASS COUNTY LAND CORNER RECORD

T. 137 R. 31 M. 5TH Coordinates: X _____ Y _____
E 1/4 21 Corner common to sections 21, 22



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

| Species | Bearing | Trees |
|-----------------|-----------------|-------|
| <u>W. BIRCH</u> | <u>W. BIRCH</u> | |
| <u>10"</u> | <u>8"</u> | |
| <u>N 80 E</u> | <u>N 50 W</u> | |
| <u>11 LKS.</u> | <u>15 LKS.</u> | |

Original Bearing Trees Found

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |

O = Corner

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |

Bearing Trees, Reference Objects

| Species | Diameter | Bearing | Distance |
|---------|----------|---------|----------|
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |
| _____ | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____