

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. N 19

CASS COUNTY LAND CORNER RECORD

T. 137 R. 32 M. 5th Coordinates: X _____ Y _____
N 1/4 23 Corner common to sections 14, 23



EXISTING SURVEYS

Original Government Survey

Year surveyed 1870

Original monument POST

Species	Bearing	Trees
<u>ASPEN</u>	<u>ASPEN</u>	
Diameter <u>7"</u>	<u>8"</u>	
Bearing <u>N 7 E</u>	<u>S 65 W</u>	
Distance <u>57 LKS</u>	<u>107 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

○ = Corner

Subsequent Corner Restoration

Year surveyed 1913 By JOHN CURD

Location filed COUNTY SURVEY RECORD BOOK A P 592-604

Monument FIND OLD GOVT B.T. 7" ASPEN N 7 E 57 LKS
SET 2 1/2 X 4 1/8" GALV. I.P. W/ CAP AND ANCHOR

Evidence of Subsequent Corner Restoration

Year of search DEC. 1915 By _____

Township road order shows no survey

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>W. OAK</u>	<u>10"</u>	<u>S 62-37 W</u>	<u>68 73'</u>
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____