


Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration


Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Index No. V1

CASS COUNTY LAND CORNER RECORD



T. 137 R. 32 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NW 31 Corner common to sections 30, 31 AND 25, 36-137-33

EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1860  
 Original monument Post

Species	Bearing	Trees
<u>N. Pine</u>	<u>N. Pine</u>	<u>P. Pine</u>
<u>12"</u>	<u>15"</u>	<u>7'</u>
<u>55 1/2 E</u>	<u>N 81 E</u>	<u>55 S W</u>
<u>130 LKS</u>	<u>205 LKS</u>	<u>29 LKS</u>

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

**Subsequent Corner Restoration**  
 Year surveyed 1963 By Co Hwy Dept  
 Location filed Co Rd #20  
 Monument 1/2" iron rod

**Evidence of Subsequent Corner Restoration**  
 Year of search 5/2001 By CCSO  
Found 3" IP, in conc., with 1/2" rebar driven in center, down 0.4', on E CR #20 and 2' E W. of E CR #110.

**Bearing Trees, Reference Objects**

Species	Diameter	Bearing	Distance
<u>Lower pole</u>	_____	_____	_____
<u>Fence post</u>	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

**Bearing Trees, Reference Objects**

W. Gate Post	P. Pole	P. Pole	Fence Cor
_____	_____	_____	_____
<u>N 24° W</u>	<u>N 46° E</u>	<u>S 41° E</u>	<u>S 37° W</u>
<u>49.83'*</u>	<u>60.89'*</u>	<u>69.21'*</u>	<u>58.88'*</u>

\*distance to double head nail

**Subsequent Corner Restoration**  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument 1911e - Typred order shows no survey

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_