


Index No. Z1

CASS COUNTY LAND CORNER RECORD

T. 137 R. 32 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
SW 31 Corner common to sections 31



EXISTING SURVEYS

Original Government Survey  
 Year surveyed 1858  
 Original monument Post

Original Evidence Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

Bearing Trees  
 Species W. OAK ELM  
 Diameter 24" 12"  
 Bearing N46 1/2 W N84 1/2 E  
 Distance 16 LKS 32 LKS.

Original Bearing Trees Found  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

Subsequent Corner Restoration  
 Year surveyed 1917 By E. B. HARST  
 Location filed COUNTY BOOK 2 P. 64  
 Monument SET 2x48" I.M. PROPORTIONALLY  
also on microfilm - roll 115 BK 76 P. 49

Evidence of Subsequent Corner Restoration  
 Year of search 2000 AUG. By CCSO  
Found in place; 60d spk., down 0.3'. Located at approx. P.I. of N1S & E1W CR #110

Bearing Trees, Reference Objects  
 Species W. OAK B. GILEAD  
 Diameter 6"  
 Bearing N 60-30E N42-43W  
 Distance 66.2' 27.8'

Bearing Trees, Reference Objects  
 Ash Elm CFP  
 4" 9"  
 S1°E N52°E WEST  
 91.70' 144.38' 27.67'  
 \*distance pulled to dbl. hd. nail

Subsequent Corner Restoration  
 Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed \_\_\_\_\_  
 Monument Corner GPS 2/18/03 CCSO  
90d spike, flush, near PI

Evidence of Subsequent Corner Restoration Found  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_