


T. 138 R. 29 M. 5th Coordinates: X _____ Y _____
E 1/4 29 Corner common to sections 28, 29



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species N. PINE N. PINE
Diameter 18" 15"
Bearing S55E N17 3/4 W
Distance 52 LKS 199 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1-1998 By J. WALKER MN/DNR
3/4" I.D. IRON PIPE, DOWN 0.3' IN E OF
T.H. #84, 4' SOUTH OF E OF RD TO EAST
CERT. OF LOCATION DOC. # 108860

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

NAIL & DISK 10" TRIP OAK N 50° W 38.69
NAIL & DISK 4" NORWAY N 54° E 57.08
NAIL & DISK 8" NORWAY S 76° W 43.89

Subsequent Corner Restoration

Year surveyed 10/04 By B. Grivna #17253
Location filed CCSO
Monument Certificate shows monument found

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____