


Index No. V 11

CASS COUNTY LAND CORNER RECORD

T. 138 R. 29 M. 5TH Coordinates: X _____ Y _____
N 1/4 33 Corner common to sections 28, 33



○ = Corner

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1865
 Original monument POST

Bearing Trees
 Species N. PINE BL. PINE
 Diameter 15" 4"
 Bearing S75E N77E
 Distance 35 LKS 145 LKS

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration
 Year of search 1-1998 By J. WALKER MN/DNR
1-1/4" I.D. IRON PIPE & THREADED CAP
FLUSH IN E OF GRAVEL EAST-WEST ROAD
CERT. OF LOCATION DEC. # 408863

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

<u>NAIL & DISK</u>	<u>12" OAK</u>	<u>N20°W</u>	<u>59.63</u>
<u>NAIL & DISK</u>	<u>POWER POLE</u>	<u>N56°E</u>	<u>27.60</u>
<u>NAIL & DISK</u>	<u>12" OAK</u>	<u>S25°E</u>	<u>39.85</u>
<u>NAIL & DISK</u>	<u>4" OAK</u>	<u>S60°W</u>	<u>36.76</u>

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search 1999 By Landecker & ASSOC.
Cert. of Survey indicates monument
found.

Jan. 1992 D. Landecker # 17008
Cert. of survey shows monument found

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____