


Index No. V 2-3

CASS COUNTY LAND CORNER RECORD

T. 138 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
M.C. # 20 Corner common to sections 30, 31



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865  
Original monument M.C. POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>W. PINE</u>	<u>W. OAK</u>	_____	_____
Diameter	<u>32"</u>	<u>14"</u>	_____	_____
Bearing	<u>S13E</u>	<u>N45 1/2 W</u>	_____	_____
Distance	<u>74 LKS</u>	<u>70 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
PLAT - SHADY POINT  
A.W. MAULSTER 1910  
PLAT - WHITE PINE POINT  
E-A BICKLEY 1920

Re monumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_