


Index No. X 5

CASS COUNTY LAND CORNER RECORD

T. 138 R. 29 M. 5TH Coordinates: X _____ Y _____
E 1/4 31 Corner common to sections 31, 32



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument POST

Bearing Trees

Species	<u>Y. Pine</u>	_____	_____
Diameter	<u>15"</u>	_____	_____
Bearing	<u>N63 1/4 W</u>	_____	_____
Distance	<u>45.6 LKS</u>	_____	_____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed ? 1920's? By Calvert Dept.
Location filed BK# 145 - Box "Field Notes"
Monument Corner at P. 1. 3" iron pipe trees:
3" conc. & steel monuments N1W 60'

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 1911 By A. W. Mastey
Microf. fm - roll 105 BK 50 P 150
Breakdown of Section 31
also '116's Roll 105 BK 51 P. 8-15

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - DUTCHTOWN
JOHN CURO 1912

DEC 1996 M. LANDECKER
PLAT SHOWS MON FOUND

Aug 2003 B. Grivna #17253
Cert. of Surv. shows Mon. Found

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____