


Index No. A 15

CASS COUNTY LAND CORNER RECORD

T. 138 R. 30 M. 5TH Coordinates: X _____ Y _____
N 1/4 3 Corner common to sections 3 AND 34 - 139 - 30



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865

Original monument Post

Bearing Trees	
Species <u>N. Pine</u>	<u>N. Pine</u>
Diameter <u>18"</u>	<u>20"</u>
Bearing <u>S47E</u>	<u>N4 1/2 E</u>
Distance <u>129 LKS</u>	<u>106 LKS</u>

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed 1912 By Harry Todd

Location filed micro film - roll 115 BK738.56-57

Monument Endstumps of Both B.T.S - set the corner

Evidence of Subsequent Corner Restoration

Year of search 6/2000 By CCSO

Set telpar mon. with Alum. cap, down 0.3', 6'E N. of & Rd. grade.

Bearing Trees, Reference Objects

Species _____	_____	_____	_____
Diameter _____	_____	_____	_____
Bearing _____	_____	_____	_____
Distance _____	_____	_____	_____

Bearing Trees, Reference Objects

<u>R. Oak</u>	<u>R. Oak</u>	<u>R. Oak</u>	<u>Aspen</u>
<u>5"</u>	<u>10"</u>	<u>8"</u>	<u>10"</u>
<u>N72°W</u>	<u>N20°E</u>	<u>N85°E</u>	<u>S24°E</u>
<u>114.91'*</u>	<u>130.67'*</u>	<u>142.91'*</u>	<u>27.74'*</u>

* distance to double head nail

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____