

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. ER1

CASS COUNTY LAND CORNER RECORD

T. 138 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 11 Corner common to sections 1, 2, 11, 12



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	Bearing	Trees
<u>BL. PINE</u>	<u>W. BIRCH</u>	<u>BL. PINE</u>
Diameter <u>5"</u>	<u>3"</u>	<u>6"</u>
Bearing <u>N14 1/2 E</u>	<u>N47W</u>	<u>S37W</u>
Distance <u>67 LKS.</u>	<u>31 LKS.</u>	<u>39 LKS.</u>

Original Bearing Trees Found

Species	Bearing	Trees
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed _____ By ROAD SURVEY
Location filed COUNTY BOOK 2 P 365
Monument 1 Red Monument

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Bearing Trees, Reference Objects

Species	Bearing	Reference Objects
_____	_____	_____
Diameter _____	_____	_____
Bearing _____	_____	_____
Distance _____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

July 2004 Jim Kramer
Section Subdivision shows RLS Bruce
Grivna at intersection of roadways

Nov. 2003 J. Kramer # 23668
Cert. of Sur. Shows mon. found

Aug. 2003 B. Grivna # 17253
Cert. of Sur. Shows mon. set and
marked RLS 17253.

Jan. 2004 B. Grivna # 17253
Cert. of Sur. Shows mon. (set)?

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____