Index No. 6 25 CASS COUNTY LAND	CORNER RECORD
7 138 0 30 M STH Condition V	<b>y</b>
T. <u>138 R. 30 M. 57H.</u> Coordinates: X. Elly 12 Corner common to sections <u>12 Ano</u> 7	130-29
CTY / Corner common to sections / AND 1	- 1 30 ~ 1
EXISTING	SURVEYS
Original Government Survey	Original Evidence Found
Year surveyed 1865	Year of searchBy
Original monument Post	
Original monument_7527	Monument found
	O = Corner
Bearing Trees	Original Bearing Trees Found
Species N. hor Bearing Trees	Species
Diameter 18"	Diameter
Bearing 365€	Bearing
Distance 142 Lks	Distance
Distance	0.910.104
C. Annana L. Orana and C. Annana and C. Anna	
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration
Year surveyed 1998 By Landecker 17008	Year of searchBy
Location filed CCSO	
Monument Certificate of Survey indicates	
monument found	
	1
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species	
Diameter	
Bearing	
Distance	
013101(08	
Location filed  Monument  March 2004 Jim Kramer  Sec Subdivision Shows computed corner  Nov. 2003 Jim Kramer # 23668  Cert. of Sur. Shows mon. found	
Remonumentation certificate prepared	By