


Index No. J 13

CASS COUNTY LAND CORNER RECORD



T. 138 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 16 Corner common to sections 9, 10, 15, 16

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	<u>N. PINE</u>	<u>OAK</u>	<u>N. PINE</u>	<u>DEAD PINE</u>
Diameter	<u>10"</u>	<u>6"</u>	<u>15"</u>	<u>15"</u>
Bearing	<u>N4E</u>	<u>N42W</u>	<u>S89W</u>	<u>S17E</u>
Distance	<u>240 LKS</u>	<u>180 LKS</u>	<u>183 LKS</u>	<u>11 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1924 By GREENE
Location filed COUNTY BOOK 'D' P143
Monument FIND CORNER

Evidence of Subsequent Corner Restoration

Year of search 1917 By John Curo
Microfilm - Roll 105 - BK Cess. 2 P. 55
Find NE & SW BITS and line tree about 200'
West set corner set I.M.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance

J-13

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search 2/6/92 By David Landecker
Found 1/2" iron pipe flush to ground 1' 5"ly
of fence line. TIES: 8" Red Oak N11E 14.65'
3" Burr Oak N72E 31.11'; 8" Red Oak stump
S80E 8.22'; 4" Burr Oak S25W 15.22'
Doc. # 336058.

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____