


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found


Year of search _____ By _____
Location filed:
Monument:

Index No. J 5

CASS COUNTY LAND CORNER RECORD

T. 138 R. 30 M. 5TH Coordinates: X _____ Y _____

NE 18 Corner common to sections 7, 8, 17, 18



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	N. Pine	N. Pine	N. Pine	N. Pine
Diameter	<u>18"</u>	<u>20"</u>	<u>20"</u>	<u>10"</u>
Bearing	<u>N54E</u>	<u>N57W</u>	<u>S66E</u>	<u>S68W</u>
Distance	<u>44 LKS</u>	<u>19 LKS</u>	<u>28 LKS</u>	<u>18 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1913 By John Luro
Location filed COUNTY SURVEY RECORD BOOK 8" P. 289-300
Monument FIND OLD CORNER B.T. STUMPS: 18" N. PINE N54E 44 LKS, 20" N. PINE N57W 19 LKS, 20" N. PINE S66E 28 LKS 10" N. PINE S68W 18 LKS SET BY 48" GALV. I.P. W/ CAPIN CONCRETE

Evidence of Subsequent Corner Restoration

Year of search 1917 By John Luro
MICROFILM - Roll 105 - BK - Cass 2 P. 61
Iron monument

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration J-5

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____