


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. N 21

CASS COUNTY LAND CORNER RECORD

T. 138 R. 30 M. 574 Coordinates: X _____ Y _____
NE 23 Corner common to sections 13, 14, 23, 24



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>BL. PINE</u>	<u>BL. PINE</u>	<u>BL. PINE</u>	<u>BL. PINE</u>
Diameter	<u>12"</u>	<u>14"</u>	<u>14"</u>	<u>12"</u>
Bearing	<u>N 30 1/2 E</u>	<u>N 11 W</u>	<u>S 43 1/2 W</u>	<u>S 53 E</u>
Distance	<u>27 LKS.</u>	<u>23 LKS.</u>	<u>54 LKS.</u>	<u>28 LKS.</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1914 By Curro
Location filed microfilm - call 115 BK 92 P. 14
Monument start E. from corner

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument Sept. 2002 R. Mustonen # 11946
Cert. of Surv. shows Mon. found

Evidence of Subsequent Corner Restoration Found

Year of search May 1905 By NW Hicks
Twp rd order shows survey
June 1908 John W Curd
Twp rd order indicates corner

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____