

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found


Year of search _____ By _____
Location filed:
Monument:

Index No. P 17

CASS COUNTY LAND CORNER RECORD

T. 138 R. 30 M. 5TH Coordinates: X _____ Y _____

E 1/4 22 Corner common to sections 22, 23



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species J. Pine
Diameter 9"
Bearing S 80 W
Distance 64 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1913 By JOHN Curo
Location filed COUNTY SURVEY RECORD BOOK B P. 289-300
Monument FIND OLD GOVT. B.T.: 9" BL. PINE S 80 W 64 LKS
AND STAKE, SET 2x48" GALV. IRON CONCRETE
1907 JOHN Curo BOOK B P. 345-349 FIND OLD GOVT
B.T.: STUMP 9" BL. PINE S 80 W 64 LKS SET 6' LAMB POST

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration

Year of search 1919 By Curo
microfilm - roll 115 BK 91 P. 12

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

P-17

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
PLAT - MILDRED
JAMES W. FIELD 1902

Certificate - Walt Curo - 1985

Find 2 1/2" Cupred I.P.
sign post East 1'

3" W. Oak S 80 W 40.15'

5" W. Oak S 42 W 30.35'

Doc. # 286250

Mar 2003 B. Grinn # 17258
Cert. of Sur. shows Mon. found

Aug 2005 B. Grinn # 17258
Cert. of Sur. shows Mon. found

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____