


Index No. R 15

CASS COUNTY LAND CORNER RECORD

T. 138 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N' 14 27 Corner common to sections 22, 27



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species Bl. Pine N. Pine \_\_\_\_\_  
Diameter 14" 14" \_\_\_\_\_  
Bearing S72W N20W \_\_\_\_\_  
Distance 46 LKS. 57 LKS. \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1913 By John Curo  
Location filed County Survey Record Book B' P. 289-300  
Monument Found Govt B.T. 14" N. Pine N20W 57 LKS.  
Set 2 1/2 x 40" G.A.W. 1, P. w/cap in concrete  
1917, E.B. Horst Book B' P. 598 Fnd. I.M.

Evidence of Subsequent Corner Restoration

Year of search 1924 By Minn. Har Dept  
R/W map in Recorder's office - Lot map to Pine River  
iron pipe w/cap 1553.0' W. of road.

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument Mar 2003 B. Grivas #17253  
Cert of Svy shows mon. found

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Re monumentation certificate prepared \_\_\_\_\_

Filed at \_\_\_\_\_

By \_\_\_\_\_

Date \_\_\_\_\_