


Index No. R 19

CASS COUNTY LAND CORNER RECORD

T. 138 R. 30 M. 5TH Coordinates: X _____ Y _____
N 1/4 26 Corner common to sections 23, 26



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1865
 Original monument POST

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Bearing Trees
 Species BL. PINE BL. PINE
 Diameter 8" 9"
 Bearing N10W S37E
 Distance 27LKS 18LKS

Original Bearing Trees Found
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Subsequent Corner Restoration
 Year surveyed 1907 By JOHN CRO
 Location filed COUNTY BOOK "B" P. 345-349
 Monument FOUND OLD CORNER BITS: 8" BL. PINE N10W
27LKS, 9" BL. PINE S37E 18LKS

Evidence of Subsequent Corner Restoration
 Year of search 1911 By A. W. Mustonen
microfilm roll 105 BK 50 P 105
Found SE BIT standing green
set 2" galv pipe in cement.

Bearing Trees, Reference Objects
 Species _____
 Diameter _____
 Bearing _____
 Distance _____

Bearing Trees, Reference Objects

R-19

Subsequent Corner Restoration
 Year surveyed 5/2000 By CCSO
 Location filed file #99053
 Monument Found 1/2" IP, down 0.2', also
NE & SE 1978 witnesses, add the following
"X" in W. end Culvert S43°W, 33.56'

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____
CERTIFICATE - AL WELLE - MINN DOT - 1978
Found 1/2" capped pipe (down 0.2') over 2 1/2"
capped pipe TIES: Fence post NW 51.51';
Fence post NE 31.61'; power pole SE 70.77'
Doc. #240559.

Mar. 2003 B. Grivna #17253
Cert. of Surv. shows Mon. Found

1999 - LANDECKER (C of S #470) indicates
iron monument fnd. in place

Aug 2003 B. Grivna #17253
Cert. of Surv. shows Mon. Found

May 2004 R. Mustonen #11946
Cert. of Survey shows monument found

Dec. 2004 R. Mustonen #11946
Cert. of Survey shows monument found

Remonumentation certificate prepared _____
 Filed at _____

By _____
 Date _____