


T. 130 R. 30 M. 5th Coordinates: X _____ Y _____
NE 26 Corner common to sections 23, 24, 25, 26



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1865
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>BL. PINE</u>	<u>BL. PINE</u>	<u>BL. PINE</u>	<u>BL. PINE</u>
Diameter	<u>4"</u>	<u>4"</u>	<u>5"</u>	<u>4"</u>
Bearing	<u>N63E</u>	<u>N44W</u>	<u>S65W</u>	<u>S40E</u>
Distance	<u>17 LKS.</u>	<u>24 LKS.</u>	<u>27 LKS.</u>	<u>7 LKS.</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1907 By JOHN CURO
Location filed COUNTY BOOK B P345-349
Monument FIND OLD GUNT BITS SET POST

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

R-21

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

R 21

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MINN DOT - AL WELGE - 1978
Found 2 1/2" capped iron pipe TIES: Fence
post NW 44.77'; Fence post NE 58.56';
10" Norway Pine S'y 44.66'; 14" Norway
PINE SE 67.37'.
Doc. #240558.

June 1908 John W. Curo
Typ rd order indicates corner