


Index No. A 17

CASS COUNTY LAND CORNER RECORD

T. 138 R. 31 M. 5TH Coordinates: X Y
NE 3 Corner common to sections 2, 3 AND 34, 35-139-31



○ = Corner

EXISTING SURVEYS

Original Government Survey
Year surveyed 1865
Original monument POST

Original Evidence Found
Year of search _____ By _____
Monument found _____

	Bearing	Trees	
Species	<u>BL.OAK</u>	<u>BL.OAK</u>	<u>W.PINE</u>
Diameter	<u>10"</u>	<u>7"</u>	<u>30"</u>
Bearing	<u>N58E</u>	<u>N8 1/2 W</u>	<u>S80W</u>
Distance	<u>31 LKS.</u>	<u>34 LKS.</u>	<u>27 LKS.</u>

Original Bearing Trees Found	
Species	_____
Diameter	_____
Bearing	_____
Distance	_____

Subsequent Corner Restoration
Year surveyed 1915 By JOHN LUKO
Location filed COUNTY RESURVEY "E-47"
Monument 2 1/4 X 4 1/8" IRON MONUMENT
1915, DENNER, BOOK D P 19 FND SQUARED SPURVE FOR CORNER
also on microf, Im - roll 105 BK 57 P 34
Distance from NW 3 & NE 1

Evidence of Subsequent Corner Restoration
Year of search 1984 By Freeman - Max.com
Survey Tech - Forester
Fnd 2" copper Pipe leaning Southwesterly

Bearing Trees, Reference Objects
Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees	Reference Objects
<u>R.oak</u>	<u>R.oak</u>
<u>13"</u>	<u>11"</u>
<u>S35E</u>	<u>S75W</u>
<u>19.55'</u>	<u>24.80'</u>
	<u>2.95'</u>

CCLD Tag

Subsequent Corner Restoration
Year surveyed MAR 6, 2003 By JILL @ LANA
Location filed _____
Monument FOUND MON. IN GOOD CONDITION

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____