Index No. B-20

CASS COUNTY LAND CORNER RECORD

T. 138N R. 31W M. 5th Coordinates: X _____ Y _____

NE 1/16 Corner common to sections 2



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1915 By J. Cora

Location filed CCSO

Monument 2 1/4" I.M.

Evidence of Subsequent Corner Restoration

Year of search 1999 By CCSO

Fd 2 1/4" OD. I.P. 4' East of ℄ Trail

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

Maple	W. Oak
6"	5"
N 79° W	S 35° W
31.82*	28.65*

*distance to double head nail

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____

Filed at _____ Date _____