


Index No. C-19

CASS COUNTY LAND CORNER RECORD

T. 138N R. 31W M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
C 1/4 Corner common to sections 2



EXISTING SURVEYS

Original Government Survey  
Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed 1915 By J. Coro  
Location filed CCSO  
Monument 2 1/4" I.M.

Evidence of Subsequent Corner Restoration  
Year of search 1999 By CCSO  
Fd 2 1/4" O.D. I.P. Up 2.9' on N. edge  
of low ground.

Bearing Trees, Reference Objects  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects  
R. Oak R. Oak W. Oak  
4" 6" 4"  
N40°W N13°E N85°E  
24.60\* 37.95\* 21.93\*  
\*distance to double head nail

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_