


Index No. E 22-23

CASS COUNTY LAND CORNER RECORD

T. 138 R. 31 M. 5TH Coordinates: X _____ Y _____
M.C.# 6 Corner common to sections 1, 12



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST M.C.

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species N. Pine
Diameter 10"
Bearing N35W
Distance 60 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1915 By DENVER
Location filed BOOK "O" P. 17
Monument END CORNER P. 20 END B.T. STANDING GREEN
SET 2 1/2 x 48" I.M. (P. 21)
also on microf. Im Roll 105 BK 53 P. 12, 27
set M.C. P. 39 set 2 1/4 x 48" I.M. w/ cap

Evidence of Subsequent Corner Restoration

Year of search 1922 By _____
Co DITCH SURVEY BK 97 BOX 2 OF Co
DITCH SURVEY BOOKS, PG 28

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____