


Index No. A 9

CASS COUNTY LAND CORNER RECORD

T. 138 R. 32 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 5 Corner common to sections 4, 5 AND 32, 33 - 139 - 32



EXISTING SURVEYS

Original Government Survey

Year surveyed 1860  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

	Bearing Trees			
Species	<u>TAM.</u>	<u>TAM.</u>	<u>TAM.</u>	<u>ELM.</u>
Diameter	<u>4"</u>	<u>6"</u>	<u>5"</u>	<u>7"</u>
Bearing	<u>N7W</u>	<u>N3E</u>	<u>S32E</u>	<u>S 91/2W</u>
Distance	<u>212 LKS</u>	<u>205 LKS</u>	<u>723 LKS</u>	<u>89 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1908 By JOHN CURD  
Location filed COUNTY SURVEY RECORD BOOK "A" P 418-424  
Monument SET 4X4X4B" POST FROM OLD GOV. B.T. ELM S.W.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_