


Index No. C 13

CASS COUNTY LAND CORNER RECORD

T. 138 R. 32 M. 5TH Coordinates: X _____ Y _____
E 1/4 4 Corner common to sections 3,4



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	Distance
<u>TAM</u>	<u>TAM</u>		
<u>12"</u>	<u>10"</u>		
<u>S47E</u>	<u>S87W</u>		
<u>4 LKS</u>	<u>6 LKS</u>		

Species	Bearing	Trees	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search MAY 1997 By K. DONAGHUE MN/DOT
SET ALUM CAPPED SQUARE STEEL 2" TUBE
MON. AT LOST POSITION.
CERT. OF LOCATION DOC. # 433374

Bearing Trees, Reference Objects

Species	Bearing	Trees	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

<u>N4D</u>	<u>4" ASPEN</u>	<u>N17°E</u>	<u>25.85</u>
<u>N4D</u>	<u>3" ASPEN</u>	<u>S64°E</u>	<u>25.47</u>
<u>N4D</u>	<u>4" ASPEN</u>	<u>S88°W</u>	<u>47.44</u>
<u>N4D</u>	<u>4" ASPEN</u>	<u>N33°W</u>	<u>21.74</u>
	<u>STEEL FENCE POST</u>	<u>SOUTH</u>	<u>1.0</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____