


Index No. L 25

CASS COUNTY LAND CORNER RECORD

T. 138 R. 3R M. 5TH Coordinates: X _____ Y _____
E 1/4 13 Corner common to sections 13 and 18-138-31



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1860
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>SPRUCE</u>	<u>W. BIRCH</u>	_____
Diameter	<u>12"</u>	<u>10"</u>	_____
Bearing	<u>S50W</u>	<u>N50E</u>	_____
Distance	<u>25 LKS</u>	<u>35 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1917 By E. B. Horst
Location filed County Book C P 63
Monument Set I.M. 2x48"

Evidence of Subsequent Corner Restoration

Year of search 7/05 By CCSO #2004, 083
Set 1 1/8" ODIP, down 0.3', 1'± E.
of E Co. Rd #112.

also on microf. film - roll 115 BK 76 P. 40

Bearing Trees, Reference Objects

Species	<u>W. PINE</u>	<u>J. PINE STUMP</u>	_____
Diameter	<u>12"</u>	<u>10"</u>	_____
Bearing	<u>N47-30W</u>	<u>S87-30E</u>	_____
Distance	<u>74.8'</u>	<u>20.1'</u>	_____

Bearing Trees, Reference Objects

<u>B. Oak</u>	<u>P. Pole</u>	<u>Twin Maple</u>	_____
<u>12"</u>	<u>8"</u>	_____	_____
<u>N65°W</u>	<u>N31°E</u>	<u>S62°W</u>	_____
<u>64.94'*</u>	<u>102.04'*</u>	<u>59.70'*</u>	_____

*distance to double head nail

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared A000667187

Filed at _____ Date _____