


Index No. N 25

CASS COUNTY LAND CORNER RECORD

T. 138 R. 32 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 24 Corner common to sections 13, 24 AND 18, 19-138-31



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1860  
Original monument 6" W. BIRCH

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Tree	Distance
<u>W. BIRCH</u>	<u>W. BIRCH</u>	<u>W. BIRCH</u>	<u>W. BIRCH</u>
<u>8"</u>	<u>8"</u>	<u>6"</u>	<u>4"</u>
<u>N52E</u>	<u>N30W</u>	<u>S80W</u>	<u>S53E</u>
<u>10 LKS</u>	<u>25 LKS</u>	<u>20 LKS</u>	<u>31 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1917 By E. B. HORST  
Location filed COUNTY BOOK "C" P 63  
Monument SET I.M. 2x48"

also on microfilm - roll 115 BK76 P.39

Evidence of Subsequent Corner Restoration

Year of search 7/05 By CCSO #2004.083  
Found 2" ODIP, top 0.8' broken off, down 1.0', 2' ± E. of S. Co. Rd #112, 9' ± E. of 12th St. Place top 0.8 vertical on top of monument.

Bearing Trees, Reference Objects

Species	Bearing	Tree	Distance
<u>J. Pine</u>	<u>J. Pine</u>	<u>J. Pine</u>	_____
<u>6"</u>	<u>5"</u>	<u>6"</u>	_____
<u>N59-15E</u>	<u>N49-30W</u>	<u>S76-30W</u>	_____
<u>35.5'</u>	<u>42.0'</u>	<u>89.8'</u>	_____

Bearing Trees, Reference Objects

Species	Bearing	Tree	Distance
<u>R. Oak</u>	<u>N. Pine</u>	<u>N. Pine</u>	<u>B. Oak</u>
<u>10"</u>	<u>12"</u>	<u>19"</u>	<u>8"</u>
<u>N47°E</u>	<u>S41°E</u>	<u>S68°W</u>	<u>N65°W</u>
<u>114.84'*</u>	<u>104.30'*</u>	<u>100.27'*</u>	<u>113.21'*</u>

\*distance to double head nail

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

Filed at \_\_\_\_\_

By \_\_\_\_\_

Date \_\_\_\_\_