


Index No. R 23

CASS COUNTY LAND CORNER RECORD

T. 138 R. 32 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 1/4 25 Corner common to sections 24, 25



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1870  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

		Bearing Trees	
Species	<u>Bl. Pine</u>	<u>Bl. Pine</u>	_____
Diameter	<u>7"</u>	<u>10"</u>	_____
Bearing	<u>N 61/2 E</u>	<u>S 75 1/2 W</u>	_____
Distance	<u>22 LKS</u>	<u>53 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 12/04 By CCSO  
Location filed #2004.083  
Monument Found 2" OD IP, up 1.2', at  
corner of Pine plantation, 1/2  
E. of Wood Post.

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects

Species	<u>N. Pine</u>	<u>N. Pine</u>	<u>N. Pine</u>
Diameter	<u>8"</u>	<u>6"</u>	<u>6"</u>
Bearing	<u>N 23° E</u>	<u>S 37° W</u>	<u>N 61° W</u>
Distance	<u>30.64*</u>	<u>31.70*</u>	<u>40.48*</u>

Bearing Trees, Reference Objects

_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_  
Filed at \_\_\_\_\_

By \_\_\_\_\_  
Date \_\_\_\_\_