


Index No. R 25

CASS COUNTY LAND CORNER RECORD

T. 138 R. 32 M. 5TH Coordinates: X NE 25 Y W.C.
Corner common to sections 24, 25 and 19, 30-138-31
0.90 CH. NORTH



EXISTING SURVEYS

Original Government Survey

Year surveyed 1860
Original monument W.C. Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees	
Species <u>Aspen</u>	<u>Aspen</u>
Diameter <u>6"</u>	<u>6"</u>
Bearing <u>N71-45W</u>	<u>N61-05E</u>
Distance <u>61 LKS</u>	<u>65 LKS.</u>

Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1917 By E.B. Hurst
Location filed COUNTY BOOK C P 63
Monument SET 2x48" I.M. 2x48"
also on microfilm - roll 115 BK 76 P. 39

Evidence of Subsequent Corner Restoration

Year of search 6/05 By CCSO #2004.083
Found 2" ODIP, down 6', bent 1.5'
from top, on E Co. Rd #112, 3' E
S. of fence line West. Set 1 1/8"
ODIP at surface.

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects		
Species <u>N. PINE</u>	<u>J. PINE</u>	<u>J. PINE</u>
Diameter <u>12"</u>	<u>8"</u>	<u>8"</u>
Bearing <u>N15E</u>	<u>N39W</u>	<u>S61-30E</u>
Distance <u>77.0'</u>	<u>85.4'</u>	<u>120.2'</u>

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects		
<u>B. Oak</u>	<u>Gate Post</u>	<u>P. Post</u>
<u>14"</u>		
<u>N41°W</u>	<u>N33°E</u>	<u>S45°E</u>
<u>50.99'*</u>	<u>98.98'*</u>	<u>58.65'*</u>

*distance to double head nail

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____