


Index No. X 13

CASS COUNTY LAND CORNER RECORD

T. 130 R. 32 M. 5TH Coordinates: X _____ Y _____
E 1/4 33 Corner common to sections 33, 34



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1870
 Original monument Post

Bearing Trees

Species	<u>BL. PINE</u>	<u>BL. PINE</u>	
Diameter	<u>6"</u>	<u>8"</u>	
Bearing	<u>S 53 1/2 W</u>	<u>N 53 E</u>	
Distance	<u>64 LKS</u>	<u>86 LKS.</u>	

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

O = Corner

Subsequent Corner Restoration
 Year surveyed 3/2001 By CCSO
 Location filed file # 2000.019
 Monument Found 4" wide, curved, piece of cast iron (possibly old water pipe), down 0.1', on E CR #111.

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>W. Oak</u>	<u>P. Pole</u>	<u>Fence</u>
Diameter	<u>8"</u>		<u>Post</u>
Bearing	<u>S 52° E</u>	<u>N 19° E</u>	<u>N 54° W</u>
Distance	<u>94.12'</u>	<u>121.84'</u>	<u>41.75'</u>

* distance to double head nail

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____