


Index No. A 13

CASS COUNTY LAND CORNER RECORD



T. 139 R. 25 M. 5TH Coordinates: X NE 4 Y 3, 4 AND 33, 34-140-25
 Corner common to sections 3, 4 AND 33, 34-140-25

EXISTING SURVEYS

Original Government Survey
 Year surveyed 1863
 Original monument POST

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Species	Bearing Trees			
	<u>BL. OAK</u>	<u>BR. OAK</u>	<u>BL. OAK</u>	<u>MAPLE</u>
Diameter	<u>7"</u>	<u>6"</u>	<u>7"</u>	<u>6"</u>
Bearing	<u>N40E</u>	<u>S48E</u>	<u>S32W</u>	<u>N52W</u>
Distance	<u>53 LKS</u>	<u>57 LKS</u>	<u>35 LKS</u>	<u>38 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed 1937 By CCC
 Location filed Washburn Lake - #1 P. 10
 Monument Set 4" oak stake w/ tag - could not find
J.P. - too much snow

Evidence of Subsequent Corner Restoration
 Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration
 Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found
 Year of search _____ By _____