


Index No. A 21

CASS COUNTY LAND CORNER RECORD



T. 139 R. 25 M. 5TH Coordinates: X _____ Y _____
NE 2 Corner common to sections 1, 2 AND 35, 36-190-25

EXISTING SURVEYS

Original Government Survey			
Year surveyed	<u>1863</u>		
Original monument	<u>Post</u>		
Bearing Trees			
Species	<u>SPRUCE</u>	<u>ASPEN</u>	<u>TAM</u>
Diameter	<u>6"</u>	<u>6"</u>	<u>4"</u>
Bearing	<u>N60E</u>	<u>N60W</u>	<u>S80E</u>
Distance	<u>12 LKS.</u>	<u>11 LKS</u>	<u>17 LKS</u>

Original Evidence Found	
Year of search	By _____
Monument found	_____
Original Bearing Trees Found	
Species	_____
Diameter	_____
Bearing	_____
Distance	_____

○ = Corner

Subsequent Corner Restoration	
Year surveyed	<u>1916</u>
By	<u>JOHN GREENE</u>
Location filed	<u>COUNTY BOOK "B" P. 530-531</u>
Monument	<u>FIND 3 BITS</u>

Evidence of Subsequent Corner Restoration	
Year of search	<u>1937</u>
By	<u>CCC - Lake Washburn</u>
Find	<u>SE SW BITS now 4 & 6" Yellow tag on 4" Spruce to mark sec. cor.</u>
	<u>BK # 1 P. 12 Cor. is 79.47' from east</u>

Bearing Trees, Reference Objects		
Species	<u>SPRUCE</u>	<u>TAM</u>
Diameter	<u>6"</u>	<u>6"</u>
Bearing	<u>S80E</u>	<u>S80W</u>
Distance	<u>81'</u>	<u>122.6'</u>

Bearing Trees, Reference Objects		
Species	<u>SPRUCE</u>	
Diameter	<u>6"</u>	
Bearing	<u>S63E</u>	
Distance	<u>124 LKS</u>	

Subsequent Corner Restoration	
Year surveyed	<u>1936</u>
By	<u>CCC</u>
Location filed	<u>Washburn Lake - BK # 3 P. 14</u>
Monument	<u>at 5240' from S. SA stake to 121' east</u>
	<u>BITS: Tag on 4" spruce N3E 121'</u>
	<u>Tam stub (scribed) S81E 8'</u>
	<u>old Tam (scribed) S7W 11'</u>

Evidence of Subsequent Corner Restoration Found	
Year of search	By _____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____

Remonumentation certificate prepared _____ By _____
 Filed at _____ Date _____