


Index No. E 5

CASS COUNTY LAND CORNER RECORD

T. 139 R. 25 M. 5TH Coordinates: X _____ Y _____
NE 7 Corner common to sections 5, 6, 7, 8



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing	Trees	
Species	<u>TAM</u>	<u>TAM</u>	<u>TAM</u>
Diameter	<u>7"</u>	<u>4"</u>	<u>5"</u>
Bearing	<u>N68E</u>	<u>S56E</u>	<u>S76W</u>
Distance	<u>37 LKS</u>	<u>21 LKS</u>	<u>14 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Washburn Lake - BK# 4 P. 2
Monument Set aspen for sec. cor. at 5280 from W.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____