


T. 139 R. 25 M. 5TH Coordinates: X _____ Y _____
NE 14 Corner common to sections 11, 12, 13, 14



EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument lost

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing Trees			
	<u>W. CEDAR</u>	<u>SPRUCE</u>	<u>SPRUCE</u>	<u>CEDAR</u>
Diameter	<u>6"</u>	<u>6"</u>	<u>4"</u>	<u>12"</u>
Bearing	<u>N60E</u>	<u>N45W</u>	<u>S75E</u>	<u>S50W</u>
Distance	<u>25 LKS</u>	<u>34 LKS</u>	<u>24 LKS</u>	<u>27 LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1911 By JOHN CURG
Location filed COUNTY SURVEY RECORD BOOK "A" P. 349-352
Monument Find Corner Set by CURG BEFORE FROM
ROAD GOVT B.T.S: 6" CEDAR N60E 16.5', 6" SPRUCE
N45W 22.4'
BOOK "B" P. 92-93 GOV. A. RALPH TIES- SEE BOOK "B" P. 92-93

Evidence of Subsequent Corner Restoration

Year of search 1916 By JOHN GREENE
COUNTY BOOK "B" P. 530-531 FIND TRUE CORNER
1937 - CCC - Washburn Lake BK#1 P. 65
Find sq wooden stake in middle of road at 5280'
from east Find 2 bearing posts (below)

Bearing Trees, Reference Objects

Species _____
Diameter 1911 - also on microfilm - vol 115
Bearing BK 74 P. 10-11
Distance _____

Bearing Trees, Reference Objects

4' high bearing post 2' high
bearing post
N47W 40'
S46E 40'

J-21

Subsequent Corner Restoration

Year surveyed 1938 By CCC
Location filed Washburn Lake - BK# 20
Monument corner in RD - Find 2 bearing posts - NW &
SE

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____