ndex No CASS COUNTY I	LAND CORNER RECORD
120 26 61	
139 R. 25 M. 57H Coordinates: X N 14 17 Corner common to sections 8,17	Y
N'19/1 Corner common to sections By//	
EVIS	7.WG GUDUSYG
	TING SURVEYS
Original Government Survey	Original Evidence Found
ear surveyed <u>1863</u>	Year of searchBy
Original monument <u>Post</u>	Monument found
Bearing Trees	Original Bearing Trees Found O = Corner
Species (FOAR (EDAR	Species
Diameter 8" 7"	Diameter
Bearing N17w 54w	Bearing
Distance 37 LKS 32 LKS	Distance
Distance 3 1 - A2	U'stance
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration
	<del></del>
rear surveyed 1937 By CCC	Year of search By
Location filed Wash born Lake - BK#1 P.71	
Monument Set approx (or 2" By Isam at 2640' Fr	can uci
* *	
Bearing Trees, Reference Objects	Bearing Trees, Reference Objects
Species	[]
Diameter	
7/dilie161	<b>!I</b>
Regring	
Bearing	li di
Subsequent Corner Restoration  Year surveyed By	Evidence of Subsequent Corner Restoration Found Year of search By
Subsequent Corner Restoration  Year surveyed By Location filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration  Year surveyed By Location filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration  Year surveyed By Location filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration  Year surveyed By Location filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration  Year surveyed By Location filed	Evidence of Subsequent Corner Restoration Found
Subsequent Corner Restoration  Year surveyed By Location filed	Evidence of Subsequent Corner Restoration Found