


Index No. L13

CASS COUNTY LAND CORNER RECORD

T. 139 R. 25 M. 5TH Coordinates: X _____ Y _____
E 1/4 16 Corner common to sections 15, 16



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument POST

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species SPRUCE SPRUCE
Diameter 8" 7"
Bearing EAST S75W
Distance 7 LKS 16 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Washburn Lake - BK# 8
Monument End 1 BIT 1/2 Tam squared by corner
Set 1 1/2 x 5/8" 1/8" 2 1/2" inground w/ steel cap
pipe on N. side of squared tam stub T139
16/15

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species Palsam Cedar
Diameter 6 1/2" 9"
Bearing N56W S36E
Distance 39.7' 26.8'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____