


Index No. N 15

CASS COUNTY LAND CORNER RECORD

T. 139 R. 25 M. 5th Coordinates: X _____ Y _____
N 1/4 22 Corner common to sections 15, 22



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1863
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>FIR</u>	<u>SPRUCE</u>	_____
Diameter	<u>6"</u>	<u>6"</u>	_____
Bearing	<u>N34E</u>	<u>S12W</u>	_____
Distance	<u>21 LKS</u>	<u>8 LKS.</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1937 By CCC
Location filed Washburn lake - BK # 1 P. 61
Monument Set approx cor 3" Ash w/metal tag
2640 from east

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____